



PM2.5*6 Round head machine screw*2

M2.5*10 Double-pass nylon column*4

M2.5*5+6 Single pass nylon column*4








Cap nut *4



Small gasket*4

Big gasket*4





KM3*4 Flat head machine screw*4






PM2.5*6 Round head machine screw *4



PM3*6 Round head machine screw *8



PM4*8 Round head machine screw*4

N4 Nut*4





PM3*6 Round head machine screw*8



